	ED WATER TESTING FORM	Page / of <u>\$</u>
Sewershed: Low Level Subsewershed: LL45	Company: Savin	Date: 8 26/08
est Type: Smoke X Water	Dyed Ground Condition: Dry: Damp: We	
Manhole ID: 15M 010	Test ID: 1029 -125-	Crew: 01  Notifications Made:X_
ield Sketch: (Show all manholes v	vith numbers, blower placement location, sa esses and locations, defect locations and pl	andbag or isolation locations, street name
332	347 B (2011) HAFER	320 9
015	THE PARTY IN	124
334 338	1 2 2 2 2 2 2 2	326
HAFERST	18 18 18 18 18 18 18 18 18 18 18 18 18 1	
EER		312
HA	6 PE 013 33	A
- 012 020		A
183	#1 336 8°	188
-   2   2   3		342
	Signer 5000	
- 141/2	131	160. 3600
003	EMPELLA	18 18 18 18 18 18 18 18 18 18 18 18 18 1
003		
-		
=// \ X/		
- 369,	163	
	100	055 05
		310
	1003	25
	33	1 1 1 5 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
	3	027
	A 336	
		AA? AB BELLICE AV
	1 2	SA TO STATE OF THE PREDENCE
	Falls	
	let	107
	438	ark/ 1/////

CITY OF BALTIMORE WET WEATHER CONSENT DECREE  SMOKE AND DYED WATER TESTING FORM						Page <u>2</u> of <u>3</u>							
Sewershed: Low Level						Date: 8/26/08							
Subsewershed: <u>LL45</u>													
Test Typ	pe: Smok Watei							ondition:			Supervi	eor.	Rich Trackoe
	vvale		-	╄	Dry:_X_Damp: Wet:					Supervisor: Rich Traskos			
١	Manhole ID: <u>15M 010</u>		Test ID: <u>1029</u> <u>125</u> <u>01</u>						Crew: 01 Notifications Made: X				
Plata	Olaskaha (Ol		ll manhalan with		ara blaves	mla a a s		laastlaa as	به حاله م				
Field Sketch: (Show all manholes with numbers, blower placement location, sandbag or isolation locations, street names, building addresses and locations, defect locations and photograph numbers)													
Defect		Δ	ddress		Source	Loc	ation	Sector	Drai	nage	Severity		
No.	<u> </u>		duress		Туре	LOC	auon	Geoloi	Ar	ea	deventy	Pł	noto Number
1		МН	15M 010		10	1	2	1	30	00	1		417
											}		
			,										
			•								ĺ		•
													•
· · · · · · · · · · · · · · · · · · ·			· · · · -										
	<b>†</b>					†							
	1					<b> </b>							
						<del>                                     </del>		<u> </u>					
					· · · · · · · · ·	<del> </del>			<b></b>			<b></b>	
	1					<del> </del>			<u> </u>			<del>                                     </del>	
	†					t							
	<u> </u>					<del>                                     </del>					<u> </u>		
	<u> </u>				<u> </u>								
-	<b> </b>				<u> </u>	<del>                                     </del>							
<b></b>						$\vdash$						$\vdash$	
					<del> </del>	$\vdash$						l	
					<u> </u>	<del>                                     </del>						i –	
					<u> </u>	<del>                                     </del>					l	<del> </del>	
THE RESIDENCE	E. W. Friedlich	The state of	State of the state		OBSERV	ATIC	N C	ODES	2 2018		IFC FORES NO		
Source Type Location Sector Severity													
01 Mai	n Sewer		MH Frame	01	Paved C			Non-Pav	/ed		Public	01	No Smoke
	vice Line		Storm Drain	$\overline{}$	Asphalt			Field/Wo		02	Private		Trace
03 Cle			Catch Basin		Paved O	ther		Alley					Moderate
	vnspout		Storm MH		Driveway			Golf Cou	ırse				Major
05 Are			Storm Ditch		Sidewalk			Other				<u> </u>	
06 Dwy			Excavation	$\overline{}$	Curb	•	<del>  ' -</del>	0.0101		-	-		
07 Stai			Water Line		Yard - Fr	ront	$\vdash$		$\dashv$	-			
			Tele. Pole		Yard - Ba		<del> </del>						
	a. Interior				Yard - Si		<del>                                     </del>						

CITY OF BALTIMORE WET W SMOKE AND DYED W	Page _3 _ of _3					
Sewershed: Low Level Subsewershed: LL45	Company: Savin	Date: 8/28/08				
Test Type: Smoke X Dyed Water	Ground Condition:  Dry: X Damp: Wet:	Supervisor: Rich Traskos				
Manhole ID: 15M 010	Test ID: <u>1029</u> <u>125</u> <u>01</u>	Crew: 01  Notifications Made: X				
	bers, blower placement location, sandbag or i	solation locations, street names,				
building addresses a	nd locations, defect locations and photograph	numbers)				
		Sieral -				
	A ALLE	2000年8月17日				
	The state of the s					
2/2/2						

L